

**ARCHITECT'S FIELD REPORT**

**063**

<b>PROJECT</b>	<b>Eagle's Nest Townhouses</b> 11 Morning Glory Way & 31 Marcellina Lane Mt. Crested Butte, CO 81225	<b>DATE</b>	10/19/11
----------------	--	-------------	----------

<b>CONDITIONS</b>			
<b>DATE</b>	10/19/11	<b>TIME</b>	10:00 am
<b>WEATHER</b>	Sunny, No Clouds	<b>TEMP</b>	45 deg

<b>WORK OBSERVED</b>	
Installation of Vinyl Garage Sill at Unit 32	
<b>TRADES PRESENT</b>	
None	

<b>PARTIES</b>		
Ben White	Ben White Architecture	970-349-5378

<b>COMMENTS &amp; OBSERVATIONS</b>
<p>1. Concrete repair and vinyl sill installation at Unit 32 garage threshold.</p>

PHOTO –WORK ITEM	DESCRIPTION	ACTION
 <p>A photograph showing the entrance to a garage. The number '32' is visible above the doorway. The interior is visible, showing a concrete floor and some items inside.</p>	<p>10/19/11 – Photo 1 Unit 32 Garage</p>	<p>Note</p>
 <p>A close-up photograph of a concrete threshold. The view is looking north, showing the edge of the concrete and the floor surface.</p>	<p>10/19/11 – Photo 2 Threshold Looking North  Existing Condition</p>	<p>Note</p>
 <p>A close-up photograph of a concrete threshold. The view is looking south, showing the edge of the concrete and the floor surface.</p>	<p>10/19/11 – Photo 3 Threshold Looking South  Existing Condition</p>	<p>Note</p>
 <p>A close-up photograph of a concrete threshold. The view is looking south. A concrete repair patch is visible on the floor. A yellow bucket and a black lid are in the foreground.</p>	<p>10/19/11 – Photo 4 Threshold Looking South  Concrete repair patch in place.</p>	<p>Note</p>




PHOTO –WORK ITEM	DESCRIPTION	ACTION
	<p>10/19/11 – Photo 5 Threshold Looking North</p> <p>Concrete repair complete.</p>	<p>Note</p>
	<p>10/19/11 – Photo 6 Detail of Sewer Cleanout</p> <p>Concrete repair around cleanout.</p>	<p>Note</p>
	<p>10/19/11 – Photo 7 Threshold Looking South</p> <p>Concrete patch cures in 30 minutes. Vinyl sill is cut to width. Note application of Liquid Nails per installation instructions.</p>	<p>Note</p>
	<p>10/19/11 – Photo 8 Threshold Looking South</p> <p>Vinyl sill in place.</p>	<p>Note</p>






PHOTO –WORK ITEM	DESCRIPTION	ACTION
	<p>10/19/11 – Photo 9 Threshold Looking North</p> <p>Vinyl sill in place.</p>	<p>Note</p>
	<p>10/19/11 – Photo 10 Sewer Cleanout Detail</p> <p>Sill was cut around cleanout.</p>	<p>Note</p>
	<p>10/19/11 – Photo 11 Interior Threshold North</p> <p>Note light coming through approximately mid-span due to damaged rubber sill attached to bottom of garage door.</p>	<p>Note</p>

PHOTO -WORK ITEM	DESCRIPTION	ACTION
 <p>A photograph showing a view of the sill at the leading edge of a garage door. The floor is concrete, and the wall is white with some staining.</p>	<p>10/19/11 – Photo 12 Exterior Threshold</p> <p>View of sill at leading edge of garage door.</p>	<p>Note</p>
 <p>A photograph showing a detail of the north threshold. It highlights the location of the sill behind an existing metal threshold bar. The wall is white and shows signs of peeling paint.</p>	<p>10/19/11 – Photo 13 Detail North Threshold</p> <p>Note location of sill behind existing metal threshold bar.</p>	<p>Note</p>

END OF FIELD REPORT