

ARCHITECT'S FIELD REPORT

087

PROJECT	Eagle's Nest Townhouses	DATE	8/28/12
	11 Morning Glory Way & 31 Marcellina Lane		
	Mt. Crested Butte, CO 81225		

CONDITIONS			
DATE	8/28/12	TIME	9:30 am
WEATHER	Clear, Sunny	TEMP	52 deg

WORK OBSERVED	
Phase III Construction – Stone Installation; Electrical Meter Covers	
TRADES PRESENT	
Holgate Construction	

PARTIES			
Ben White	Ben White Architecture	970-349-5378	
Mick Holgate	Holgate Construction	970-209-4449	

COMMENTS & OBSERVATIONS

- 1. Observed continuing stone work on Building 'B'. Installation is within project tolerances. Color blend is good and stone is level.
- 2. Awaiting additional metal flashing and precast base to complete Building 'B'.
- 3. Electrical Meter covers are nearing completion.
- 4. Repairs to Unit #9 balcony are complete.
- 5. (2) Stone Masons and (2) workers were on site.
- 6. Precast base installation is 95% complete. Stone installation is progressing well ahead of schedule.
- 7. Weather Delays to Date 1 day



PHOTO –WORK ITEM	DESCRIPTION	ACTION
	8/28/12 – Photo 1 Lower Level Unit 40 Conduit Trenching and conduit complete. Awaiting backfill.	Note
	8/28/12 – Photo 2 Lower Level Unit 40 Conduit Note conduit in trench and exterior junction box in the lower right corner.	Note
k T	8/28/12 – Photo 3 Unit 17 Electrical Meter Cover Awaiting siding and roofing.	Note

PHOTO –WORK ITEM	DESCRIPTION	ACTION
TAP	8/28/12 – Photo 4 Unit 33 Electrical Meter Cover Awaiting siding and roofing.	Note
	8/28/12 – Photo 5 Unit 33 Electrical Meter Cover Photo from above.	Note
	8/28/12 – Photo 6 Unit 32 Electrical Meter Cover Photo from above.	Note
	8/28/12 – Photo 7 Unit 8 Electrical Meter Cover Awaiting roofing. Stucco patch to the left will require painting.	Note



PHOTO –WORK ITEM	DESCRIPTION	ACTION
	8/28/12 – Photo 8 Unit 9 Electrical Meter Cover Meter cover nearing completion.	Note
	8/28/12 – Photo 9 Units 9 & 10 Stone work completed on Units 9 & 10.	Note
	8/28/12 – Photo 10 Building 'B' Looking North Stone work progressing on Units 13 & 14.	Note
	8/28/12 – Photo 11 Building 'B' Looking North View of construction work zone. Some parking has been compromised.	Note



PHOTO -WORK ITEM	DESCRIPTION	ACTION
	8/28/12 – Photo 12 Unit 9 Balcony Repairs Repairs are complete. Existing siding has been reapplied. Siding above garage door was replaced with steel siding.	Note
	8/28/12 – Photo 13 Unit 9 Balcony Repairs Scupper is in good condition. Damaged wood members have been replaced.	Note
	8/28/12 – Photo 14 Unit 9 Balcony Repairs Detail Detail of corner – flashing and new steel siding are temporary.	Note
	8/28/12 – Photo 15 Upper Level Work Area Looking South Construction site is well organized and clean.	Note

END OF FIELD REPORT